These are sample MCQs to indicate pattern, may or may not appear in examination

## **University of Mumbai Online Examination 2020**

Program: BE Mechanical Engineering Curriculum Scheme: Revised 2012 Examination: Final Year Semester VIII

Course Code: MEE80210 and Course Name: World class manufacturing

Time: 1hour Max. Marks: 50

Note to the students:- All the Questions are com	npulsory and carry equal marks .
Trote to the students. All the Questions are con-	ripulsory and carry equal marks.

<b>Note to the students:-</b> All the Questions are comp	
Q	"Poka-yoke" is the Japanese term for
A	Card
В	Fool proof
С	Continuous improvement
D	Fishbone diagram
	Malcolm Baldrige national quality
Q	award is for (MBNQA)
A	Total Quality Management
В	International Standard Organization
С	Total Productive Maintenance
D	Total Quality Control
	The process mapping is a
Q	diagram.
A	Data flow
В	Work flow
С	Circular
D	Audit
	The objective of ISO-9000 family of
Q	Quality management is
A	Customer satisfaction
В	Employee satisfaction

С	Skill enhancement
D	Environmental issues
	According to Deming, Quality problems
Q	are
A	Due to management
В	Due to method
C	Due to machine
D	Due to material
	The sequence of a typical
Q	manufacturing supply chain is
	Storage–Supplier–manufacturing–stor
A	age-distributor-retailer-customer
	Supplier–Storage-
	manufacturing-storage-distributor-ret
В	ailer–customer
	Supplier–Storage-manufacturing–
С	distributor–storage–retailer–customer
	Supplier-Storage-
	manufacturing-storage-
D	retailer–distributor–customer
	The purpose of supply chain
Q	management is
A	provide customer satisfaction
В	improve quality of a product
	integrating supply and demand
C	management
D	increase production

	Due to small change in customer
	demands, inventory oscillations
	become progressively larger looking
	through the supply chain.
Q	This is known as
A	Bullwhip effect
В	Netchain analysis
C	Reverse logistics
D	Reverse supply chain
Q	VMI stands for
A	Vendor material inventory
В	Vendor managed inventory
C	Variable material inventory
D	Valuable material inventory
	The major decision areas in supply
Q	chain management are
	location, production, distribution,
A	inventory
	planning, production, distribution,
В	inventory
	location, production, scheduling,
С	inventory
	location, production, distribution,
D	marketing
	In line organisation, the business activities
	are divided into following three types
Q	
A B	Accounts, Production, Sales Production, Quality, Sales
С	Production, Quality, Maintenance
D	Production, Maintenance, Sales
U	Froduction, Maintenance, Sales

	The culture followed by a natural design
Q	system is
A	static
В	rigid
C	adaptive
D	dynamic
	Self directed team can be thought as
Q	fundamentsl work unit in the
A	Adhocrate
В	Bureaucratic organization
C	learning organization
D	diversified organization
	For efficient performance of the
Q	organization, stratergy is formulated by
A	Top management
В	Middle management
С	Administration
D	Functional managers
	Continuous learning is possible by looking
Q	at organizational design's
A	4 elements
В	5 elements
C	6 elements
D	7 elements
Q	Just-In-Time aimed at
A	Zero inventories
В	Reduced manpower
С	Over production
D	Incrased manpower
	In how many dimensions HRD maturity
	level in an organization is measured?
Q	
A	3

В	4
C	5
D	6
Q	Human resource department plays / serve as
A	Advisory role
В	line authority
C	hiring department only
D	training department only
	if company defines authority and
	communication channels for employees, it
Q	is performing
A	staffing function
В	organizing function
C	leading function
D	controlling function
	Organisation establishes relationship
Q	between
A	People, work and resources
В	Customer, work and resources
C	People, work and management
D	Customer, work and management
	'No one on the organisation should have
	more than one boss' is a statement of
Q	
A	Principle of specialisation
В	Principle of authority
С	Principle of unity of command
D	Principle of span of control
	Who among the following suggested
	seven quality tools for controlling
Q	quality?
A	Juran
В	Kaoru Ishikawa

С	Dr. W. Edward Deming
D	Feigenbaum
Q	Waterfall method is observed in
A	product design and development
В	quality circle
C	brain storming
D	flow chart
Q	Which type of chart uses the rule of 20:80?
A	cause and effect chart
В	Pareto chart
C	fish bone diagram
D	control chart
	Which award is presented to different
	organizations for quality and excellent
Q	performance by president of USA?
A	Malcolm Balbridge National Award
В	Dr. W. Edward Deming National Award
C	US Excellence Award
D	UK Excellence Award